

WYRE Making Space for Water - Hotspot List

Appendix A - Flood Hot Spot List – AUGUST 2018

1 – Live flood issues. New comments in GREEN					
Location of incident	Brief summary of the incident	Agreed action	Priority	Status	Update / Comments
Sunnyside Terrace, Preesall	<p>Sunnyside Terrace has suffered a number of flooding events which have included internal flooding to properties – the most recent event was 22 November 2017.</p> <p>LCC have obtained a grant to undertake capital works to reduce the risk of flooding.</p> <p>The MSfW Group is looking to undertake initial works to carry out works to Green Lane watercourse to ensure that there is a clear discharge point for excess flood water.</p>	<ul style="list-style-type: none"> ☐ LCC to cut back willow tree in Green Lane watercourse to allow free flow in the watercourse. ☐ LCC to undertake desilting works to culvert under Cart Gate. ☐ LCC to undertake desilting works on Green Lane watercourse, including culvert under road. WBC to inform landowners adjacent to watercourse. ☐ LCC to consider other flood mitigation works once the discharge point is cleared. ☐ LCC / EA to inspect full length of Green Lane watercourse to its discharge point to River Wyre. ☐ EA to inspect and clear if necessary river outfall. 	High	Works ongoing	<ul style="list-style-type: none"> • Willow tree has been removed from Green Lane watercourse. • Culvert under Cart Gate has been inspected and desilting works undertaken. • Desilting of watercourse not yet undertaken – LCC are waiting for results of ecology survey before any works are planned. • Landowners on Green Lane have been written to for consent to undertake works to watercourse. • LCC / EA inspection not yet undertaken. • Inspection of river outfall not yet undertaken.
Meadow Avenue, Preesall	Watercourse to rear of Meadow Ave, Preesall in urgent need of cleaning and reinstatement. Watercourse takes surface water from Pilling Lane and estate around Meadow Ave.	<ul style="list-style-type: none"> ☐ Undertake investigations ☐ Undertake appraisal to identify possible actions ☐ Possible Enforcement ☐ 	Medium	On-going	<ul style="list-style-type: none"> • LLFA (FRM Team) to investigate, potential enforcement ☐ action required. • Inspected LCC/WBC – WC to look at community payback as possible option to clear on a one-off basis. • Still outstanding. Site to be inspected as part of community walkabout on 30 May and action planned PL TO INVESTIGATE / OR WAS IT PB??? AG TO LOOK AT ENFORCEMENT ???
Pilling Lane, Preesall	Highway floods during heavy rainfall events. Road is only passable with care.	<ul style="list-style-type: none"> ☐ Undertake investigations. Consider linkage to Meadow Ave. ☐ Undertake appraisal to identify possible actions ☐ Possible Enforcement ☐ 	Medium	On-going	<ul style="list-style-type: none"> • LLFA (FRM Team) to investigate, potential enforcement ☐ action required. • Flooding presumed to be linked to Meadows Ave watercourse and to be considered as the same issue. • Still outstanding. Site to be inspected as part of community walkabout on 30 May and action planned.
Regatta Point, Hambleton	Complaints re movement of river embankment causing damage to perimeter fencing.	<ul style="list-style-type: none"> ☐ Environment Agency to undertake ☐ investigations 	Low	Completed	<ul style="list-style-type: none"> ☐ Works completed.

Location of incident	Brief summary of the incident	Agreed action	Priority	Status	Update / Comments
Lancaster Road, Preesall	<p>Flooding of fields and Lancaster Road. Road requires to be closed when flooded.</p> <p>Dykes are not draining, possibility of blockage under highway. Investigate if there is a blockage in the culvert.</p>	<ul style="list-style-type: none"> □ Undertake preliminary investigations □ Undertake appraisal to identify possible actions □ 	Medium	On-going	<ul style="list-style-type: none"> • LLFA (FRM Team) undertook initial site investigation and □ Met local residents on Tuesday 15 November. • Dyke full and very limited flow. Maintenance cannot be undertaken on network of dykes until obstruction can be found and removed. • FRM have undertaken an investigation in January 2017. Culvert under highway was cleaned out and jetted to remove silt build up. Further works are required as there is a capacity issue and the embankment is slipping into the ditch. • LCC has been made aware of their duties and will report on further action needed. • Culvert now cleared. Works required to repair culvert end wall – LCC to undertake these summer 2017. □ No recent action – works still planned for 2017/18 □ LCC to inspect to arrange works. <p>AG TO EMAIL LCC PROJECT MANAGER AND TO LET MO'D HAVE A COPY??</p>
Fordstone Road, Preesall	Complaint from resident of water under floor boards. UU investigated – suspected blocked/damaged private drain.	<p>Trash screen to be checked / cleared. Monitor</p> <ul style="list-style-type: none"> □ any change. 	Low	Monitor	<p>Trash screen to be checked / cleaned. Potential that pipe</p> <ul style="list-style-type: none"> □ under properties has collapsed – private issue but UU may be able to advise. □ Trash screen inspected – no issues □ No further action required.
Ravenswood Ave,	Reoccurrence of flooding to residential property during heavy rainfall.	<ul style="list-style-type: none"> • EA to check and clear Horse Bridge Dyke □ watercourse. • UU to check local sewers • HA to check highway drainage 	Low	No further action required	<p>Reoccurrence of past flooding incident – suspected</p> <ul style="list-style-type: none"> • private drainage issue; EA, UU and HA to check systems and advice to be given to occupant. • UU has inspected systems and spoken with resident. EA yet to check watercourse. • EA have undertaken routine maintenance to Horsebridge Dyke watercourse. No issues noted.
Normoss Road, Normoss	Flooding to residential property from surface water sewer.	<ul style="list-style-type: none"> □ LCC to inspect culverted watercourse under Normoss Road for blockages. 	Low	On-going	<ul style="list-style-type: none"> • UU has inspected assets and found no problem. Will monitor for any reoccurrence. • LCC to inspect culvert. <p>AG TO UPDATE??</p>
Derby Crescent, Inskip	Surface water flooding to residential street. Foul and surface water misconnections in local drainage leading to foul in street	<ul style="list-style-type: none"> □ LCC / UU to investigate 	Medium	On-going	<p>UU have inspected and report misconnection of highway</p> <ul style="list-style-type: none"> □ drainage and local residential property. LCC to fix connection issues; UU to contact resident to resolve misconnection. • Resident has been advised and will undertake misconnection works. • LCC to resolve misconnection of highway drainage IN 4 – 6 WEEKS TIME??

Location of incident	Brief summary of the incident	Agreed action	Priority	Status	Update / Comments
Kiln Lane / Sherbourne Road, Hambleton	Local area has suffered numerous flooding incidents resulting in internal flooding to a number of properties.	UU to consider installation of new inspection chamber on culverted watercourse for easier access	Low	New (reopened)	<ul style="list-style-type: none"> UU have inspected the banks of Wardleys watercourse and not located discharge point from culverted watercourse. Investigation works may be required to ensure that water from local area can freely discharge to watercourse. <p>UU HAVE HAD A CAMERA DOWN AND FRM TEAM. AG TO UPDATE??</p>
School Road, Thornton	Several properties on School Road flooded Nov 2017. Source of flooding appears to be surface water from local surface water drains, suspected blocked highway gullies and poor maintenance of watercourse behind properties	<p>LCC to carry out cleaning of local highway gullies</p> <ul style="list-style-type: none"> WBC to contact Network Rail re maintenance of watercourse Inspection of local drainage network to be undertaken to identify issues WBC to draft flooding report from Nov 2017 to identify issues and propose resolution. 	High	New	<ul style="list-style-type: none"> Gullies cleaned 29 May NR have responded that they are not responsible for the watercourse – WBC to pursue this further Inspection of watercourse and local drainage carried out by WBC/ Thornton FLAG 22 May Flooding report in progress – to be presented to FLAG June 2018 <p>AG AND RC TO SEND AN EMAIL TO NETWORK RAIL AND JB GAVE AG A HARD COPY OF THE SCHOOL ROAD REPORT</p>
New Lane, Thornton	Several properties on New Lane flooded Nov 2017. Source of flooding appears to be surface water from runoff from local fields, surcharged sewers and surface water drains.	<p>WBC to contact Highways England re maintenance of culverts under A585 Amounderness Way</p> <ul style="list-style-type: none"> WBC to draft flooding report from Nov 2017 to identify issues and propose resolution. 	High	New	<ul style="list-style-type: none"> HE have responded that they will undertake clearing of all culverts under A585 by late summer 2018. Inspection of watercourse and local drainage carried out by WBC/ Thornton FLAG 1 Feb 2018 – WBC to identify responsibility for all culverts on Royles Brook and Hillylaid Pool Flooding report in progress – to be presented to FLAG June 2018 <p>SEE ABOVE</p>
Carr Lane, Hambleton	Flooding to property (external only) from highway run-off.	<p>LCC to clear highway gullies on Market Street and on Carr Lane in vicinity of Market Street to improve local highway drainage</p>	Medium	New	GULLIES ALL DONE AND TO MONITOR AFTER NEXT RAINFALL
Calder Ave, Thornton	Several properties were flooded Nov 2017 – Residents have complained that highway drains contributed to the flooding and have not been cleared.	LCC to clear highway gullies on Calder Ave	Medium	New	<p>Gullies cleaned 24 May</p> <p>GULLIES ALL DONE AND TO MONITOR AFTER NEXT RAINFALL</p>